

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

JL1325  
NNE  
> 1  
1.690 mi.  
8924 ft.

MANHOLE 1428  
CONEY ISLAND AVE/AVE T  
BROOKLYN, NY

NY Spills S106470878  
N/A

Site 3 of 3 in cluster JL

Relative:  
Higher

Actual:  
19 ft.

SPILLS:

Name: MANHOLE 1428  
Address: CONEY ISLAND AVE/AVE T  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0403819 / 2004-10-04  
Facility ID: 0403819  
Facility Type: ER  
DER Facility ID: 197376  
Site ID: 239945  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2004-07-09  
Investigator: SKARAKHA  
Referred To: Not reported  
Reported to Dept: 2004-07-10  
CID: 74  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2004-07-10  
Spill Record Last Update: 2004-10-04  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: ERT DESK  
DEC Memo: "e2mis no 154262 09-JUL-2004 07:35 HRS. G.MOORE EMP# 18872 REPORTS:

Remarks:

FOUND: APPROX. 1 GAL OF UNKNOWN OIL ON APPROX. 50 GAL'S OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PUMP. NO SUMP. OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. 1 LIQ. SAMPLE TAKEN FOR PCB FROM SPILL. CLEANUP TO BE DONE AS 50-499. Lab Sequence Number: 04-05369-001: TOTAL PCB: 121 ppm 7/10/2004 01:30 HRS. -- ENV OPS CREW CLEANED STRUCTURE BUT ENV. STOP TAG REMAINS IN PLACE DUE TO OIL-SOAKED ASBESTOS ARC-PROOFING ON FEEDER. UNDERGROUND CANNOT REMOVE ARC-PROOFING AT THIS TIME BECAUSE FEEDER IS ALIVE. UPDATE: 10-JUL-2004 1856HRS T FERNENDEZ REPORTS UG WORKING IN STRUCTURE HOT. CLEANUP WITH RESUME @ 2300HOURS WHEN UG IS COMPLETE WITH REPAIRS. Gene Williams reports: Removed 2 drums of debris including a lead joint and oil soaked asbestos arc proofing from MH1428. The structure was cleaned and double washed with biogen 715 & 760. The job was complete at 05:30. Job is 100% complete. "1 Gallon of unknown oil on 50 gallons of water in a manohole. Taken off the 24 hour deminimus program - due to the amount of work to be done to clean it up. Ref. #154262 "

All Materials:

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Site ID: 239945  
Operable Unit ID: 887081  
Operable Unit: 01  
Material ID: 491377  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported